


FIG. 1








FIG. 3A




FIG. 4




FIG. 5




FIG. 6






FIG. 7





US 2017/026999 A1

AEROSOL









FIG 9


FIG. 11
















FIG 17


005007 91602310




51618




5/6/22



[illegible]

22915



00507-960230

Method of Coating	Method of Solvent Addition	Method of Dissolution	Method of Sample Acquisition	Method of Waste Disposal	Method of Washing	Method of Drying
Manual Pipetting	Manual Pipetting	Gentle Agitation	Manual Syringe	Manual	Manual	Manual
Automatic Pipetting	Automatic Pipetting	Ultrasonics	Automatic Syringe	Automatic Dumping	Standard Dishwasher	Hot Air
Pumping In Liquid; Followed by Drying Air or Nitrogen-enriched Air		Mechanical Vibration	Decanting	Suction	Special Wash Station	Hot Nitrogen-Enriched Air
		Direct Contact Rubbing				
		Recirculation				

FIG 25